INSPECTION REPORT

Partial XXX Complete Exploration Inspection Date: 05/14/2003/ Time: 9:00 – 12:00
Date of Last Inspection: 04/09/2003

Mine Name: West Ridge Mine	County: Carbo	<u>n</u> Permit Number: <u>C/0</u> 0	07/041
Permittee and/or Operator's Name: Wes	t Ridge Resources,	Inc.	
Business Address: P.O. Box 902, Price, U	tah 84501		
Company Official(s): Gary Gray			
State Official(s): Karl R. Houskeeper]	Federal Official(s): None	
Weather Conditions: Clear, Temp 79°C			
Type of Mining Activity: Underground 2	XXX Surface 1	Prep PlantOther	
Existing Acreage: Permitted 4382.55 Di	sturbed 29.06 Reg	raded Seeded	
Status: Active			

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For <u>complete inspections</u> provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For <u>partial inspections</u> check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]			
2.	SIGNS AND MARKERS	[X]		[X]	\Box
3.	TOPSOIL	[X]		[X]	
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[X]		[X]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[X]		[X] [X]	
c.	OTHER SEDIMENT CONTROL MEASURES	\Box	\Box		\Box
d.	WATER MONITORING	[X]		[X]	\Box
e.	EFFLUENT LIMITATIONS				
5.	EXPLOSIVES	[X]			
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box			\Box
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS				
8.	NONCOAL WASTE	[X]		[X]	
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES				
10.	SLIDES AND OTHER DAMAGE				
11.	CONTEMPORANEOUS RECLAMATION		\Box		
12.	BACKFILLING AND GRADING				
13.	REVEGETATION				
14.	SUBSIDENCE CONTROL		\Box		
15.	CESSATION OF OPERATIONS		\Box		
16.	ROADS:				
a.	CONSTRUCTION/MAINTENANCE/SURFACING				\Box
b.	DRAINAGE CONTROLS				
17.	OTHER TRANSPORTATION FACILITIES				
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS		\Box		
19.	AVS CHECK (4 th Quarter- April, May, June)				
20.	AIR QUALITY PERMIT				
21	BONDING & INSURANCE	[]	[]	Г <u>1</u>	[]

INSPECTION REPORT

(Continuation Sheet)

PERMIT NUMBER: <u>C/007/041</u> DATE OF INSPECTION: <u>05/14/2</u>
--

(COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE)

2. SIGNS AND MARKERS

Mine ID signs are present at the pump house and main entrance to the mine. The ID signs contained the required information. Topsoil pile storage signs are present on the topsoil pile. All other signs and posts meet the requirements and designation identified in the MRP.

3. TOPSOIL

The silt fence around the perimeter of the Topsoil Pile needs to be re-anchored at the base contact point.

4A. HYDROLOGIC BALANCE: DIVERSIONS

The diversions at the mine site have been cleaned and/or graded. One pipe was present in the diversion adjacent to the upper storage pad. The pipe size and length requires a piece of equipment to remove it from the diversion.

4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

Water is present in cell A of the sediment pond. Some mine water has been diverted into the sediment pond. This practice is now allowed since the approval of an amendment that permits treatment of mine water in the sediment pond. The water level was checked and is below the maximum allowable water level specified in the approved amendment for mine water storage.

4D. HYDROLOGIC BALANCE: WATER MONITORING

First quarter 2003 water monitoring information is in the EDI pipeline and still needs approval to be uploaded. Water monitoring at the mine site is current.

8. NONCOAL WASTE

The main facility was free of noncoal waste. A general spring cleanup for noncoal waste is needed between the Topsoil Pile and the Soil Test area.

Inspector's Signature: _	Karl R. Houskeener	#40	Date: <u>May 16, 2003</u>
	Karl R. Houskeeper	#49	

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

cc: James Fulton, OSM
Gary Gray, West Ridge
Price Field office
O:\007041.WR\Compliance\2003\p_0514.doc